


# Bond Tool Minimum and Maximum Casing Sizes



Due to variables such as well bore fluid density, casing weights and tool condition, the above values are for general tool selection.

- † Excellent signal return in ideal conditions
- ‡ Sufficient signal return in ideal conditions
- § No signal return

“Ideal Conditions” include fresh water, minimum 1000 psi hydrostatic pressure, good free pipe calibrations, proper tool centralization, and a recently serviced tool.

